



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



Case Vehicle (A): 1999 Chevrolet

Vehicle (B): 1996 Chrysler Type: Silverado, 4x4 extended cab pickup Type: Concorde, 4-door sedan

Driver: 65-year-old male Driver: 79-year-old male

CDC: 02-FDEW-2, 03-RZEW-2, 00-TDYO-3 CDC: 11-LYEW-4, 09-LZEW-2

SITUATION

(Slide 1) Case vehicle (A) was traveling west in the westbound lane of a straight section of a dry, two-lane asphalt roadway, with a speed limit of 89 kph (55 mph), and was approaching a four-leg intersection. Vehicle (B) was traveling south in the southbound lane of the intersecting two-lane roadway. (Slides 2, 3, 4) As case vehicle (A) entered the intersection, vehicle (B) also entered the intersection and crossed into the path of case vehicle (A). Case vehicle (A) struck the left side of vehicle (B) with its front end. The impact caused vehicle (B) to enter a clockwise rotation and case vehicle (A) to enter a counterclockwise rotation, resulting in a side-slap impact between the two vehicles involving the left side of vehicle (B) and the right side of case vehicle (A). Vehicle (B) crossed the eastbound traffic lane and exited the intersection through the west leg, and then departed the roadway off the south shoulder before, coming to rest on the south side of the road. Case vehicle (A) departed the roadway where it tripped, right side leading, (slide 5) and rolled four-quarter turns. Case vehicle (A) came to rest on its wheels at the southwest corner of the intersection, facing southeast.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 6) Damage to case vehicle (A) was severe. The direct-damage length for the front-end impact with the side of vehicle (B) was 150 cm, and began at the right-front bumper corner. The maximum crush was 48 cm and occurred at the right-front bumper corner. The vehicle overlap was calculated to be 80%. The right wheelbase was reduced by 14 cm, and the left wheelbase was extended by 3 cm. The direct-damage length for the side-slap impact was 106 cm and began 17-cm forward of the rear axle. The maximum crush was 24 cm and was located 50-cm forward of the rear axle. Damage from the rollover event was confined to the cab and front portion of the vehicle. Maximum crush occurred on the left portion of the roof and was 17 cm.

(Slides 7, 8) Damage to vehicle (B) was severe. The direct-damage length for the side impact with case vehicle (A) was 157 cm and began 258-cm forward of the rear axle. The maximum crush was 64 cm and occurred 154-cm forward of the rear axle. The direct-damage length for the side-slap impact was 127 cm and began 108-cm forward of the rear axle. The maximum crush was 10-cm and occurred 28-cm forward of the rear axle.

Using the WinSMASH accident-reconstruction program and (slides 9, 10, 11, 12, 13, 14, 15) c-values for case vehicle (A) and vehicle (B), the following impact severities were calculated for the frontal impact of case vehicle (A) with the side of vehicle (B):

		Calculated Velocity Change - kph (mph)			
Vehicle	Variable	Total	Longitudinal	Latitudinal	
Case Vehicle (A)	delta V	27 (17)	-17 (-11)	-21 (-13)	
Vehicle (B)	delta V	36 (22)	-28 (-17)	23 (14)	

Using the WinSMASH accident-reconstruction program and (slides 16, 17, 18, 19, 20) c-values for case vehicle (A) and vehicle (B), the following impact severities were calculated for the side-slap impact between the two vehicles:

		Calculated Velocity Change - kph (mph)			
Vehicle	Variable	Total	Longitudinal	Latitudinal	
Case Vehicle (A)	delta V	9 (6)	0 (0)	-9 (-6)	
Vehicle (B)	delta V	13 (8)	0 (0)	13 (8)	

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

(Slides 21, 22, 23, 24, 25, 26, 27) The front bumper, the right headlight assembly, the hood, the grille, the radiator, the right fender, the windshield header, both upper A- and B-pillars, and the roof were damaged by direct contact. There was induced damage to the lower right A- and B-pillars. The windshield was cracked by impact forces. The single left door remained closed and operational, but both right-side doors were jammed shut. (Slide 28) The hood latch was damaged and released. Both hood hinges were deformed, but did not separate, and the hood

remained attached to the vehicle. The rear edge of the hood was elevated, but it did not contact the windshield.

Interior

(Slides 29, 30) This vehicle was equipped with both steering-wheel and passenger frontal-impact airbags. The steering-wheel airbag deployed during the frontal impact, but the passenger frontal-impact airbag was switched off. (Slides 31, 32) No damage was noted to the airbag module doors/flaps. (Slide 33) The steering-wheel rim was not deformed. (Slides 34, 35, 36, 37, 38) The left-front door interior panel and armrest were damaged by occupant contact. Both front side windows and the right-rear side window were broken. Both upper A-pillars, the left roof siderail, and the left-side roof structure were damaged. The center console was broken loose and the vertical console and a climate control vent were damaged where the vertical console joined with the center console. A scuff mark was noted on the driver knee bolster below the steering column. (Slides 39, 40, 41) There were no occupant contact marks on the left-upper A-pillar, the windshield header/sunvisor, or the roof-mounted console. (Slide 42) The following intrusions were noted and measured:

Location	Component	Distance (cm)	Direction
left front	windshield header	6	down
	A-pillar	17	down
	roof siderail	12	down
	roof	10	down
right front	toepan	18	to rear

OCCUPANT INJURIES AND KINEMATICS

The 6-ft, 4-in, 250-lb, 65-year-old male driver (slides 43, 44) was wearing the available seat-integrated three-point belt, as indicated by damage to the seatback where the shoulder belt exits, and the steering-wheel airbag deployed. During the frontal impact, he moved forward and to the right into the belt restraints and the airbag. He sustained contusions over the left shoulder and chest from loading by the shoulder belt. He sustained two lacerations to the left forearm from an unknown source. (Slides 45, 46) He sustained a comminuted fracture of the left medial tibial condyle, from contact with the knee bolster below the steering column. (Slides 47, 48, 49, 50)

Scuff marks were noted on the interior door panel and the dislocated center console, but no injuries were reported that could be associated with these contact points.

The following table and (slide 51) attached drawing summarize the injuries sustained by the driver.

Occupant: Driver
Restraints: Seat-integrated 3-point belt worn; airbag deployed

Age: 65 years Stature: 193 cm (6 ft, 4 in)

Gender: Male Mass: 114kg (250 lb)


			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Contusion, left shoulder	1	Shoulder belt		
Contusion, left side of chest	1	Shoulder belt		
Laceration, left forearm	1		·	Unknown
Laceration, left forearm	1			Unknown
Fracture, comminuted left medial tibial condyle	3	Knee bolster		
Maximum A.I.S. Level	<u>3</u>			
Injury Severity Score	<u>10</u>			

Duplicate columns 1-8 Module <u>G I</u> Format <u>(</u> from the previous card. 9 10 1	0 2	GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION	_	ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE (0) NO (1) YES (9) UNKNOWN ROAD ALIGNMENT VERTICAL PLANE	<u>₽</u>
LOCATION STATE: STATE FIPS CODE AREA (1) URBAN (2) RURAL (9) UNKNOWN	25 26 2 27	(1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN ROAD ALIGNMENT HORIZONTAL PLANE (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER:	34
ENVIRONMENTAL CONDITIONS LIMITED-ACCESS HIGHWAY (0) NO (1) YES (9) UNKNOWN ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE) (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	<u>2</u>	(9) UNKNOWN SURFACE COVERING (10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN (31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN	36 37
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE . TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN	2 30 1	VISIBILITY LIMITATION (FOR CASE VEHICLE) (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN VISIBILITY OBSTRUCTION (FOR CASE VEHICLE) (0) NONE	<u></u>
ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	<u>Q</u>	(1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	39

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	2 48	(5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	3 55
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	<u></u>	DRIVER IMPAIRMENT DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>Q</u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN	50	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	- 8 <u>D</u> 57 58
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	<u>D</u>
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>D</u>	LIST IMPAIRMENTS MENTION	NED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	53	Post - Crash Detail Manner case vehicle Left scene	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>✓</u>	 (1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN 	2

ACCIDENT DESCRIPTION: (ase vehicle (A) was traveling westbound on a 2-lune CASE VEHICLE (A) 1999 Chevrolet Silverado road way, approaching a 41eg intersection. Vehicle (B) was traveling south sound on the OTHER VEHICLE (B): 1996 Chrysler Concorde intersecting 2-lane roadway. As case vehicle (A) entered the intersection vehicle (B) also entered the intersection and crossed the path of case vehicle (A). Case vehicle (A) struck the left side of vehicle (B) with its front end. The impact caused vehicle (B) to enter a clockwise rotation and case vehicle (A) to enter a counterclockwise rotation pin a side-slap impact between the two vehicles. Vehicle (B) crossed the east bound traffic lane and exited the intersection.

Through the west lead deported the randown and came to a rest. (ase vehicle (A) departed roadway where it tripped, right side leading NORTH a rolled 4-quarter turns. Case vehicle (A) came to rest on its wheels at the southwest corner of the intersection.



Duplicate columns 1-8 Module O V Format 0 4 from the previous card.	OTHER VEHICLE OV-1	l
MAKE: Chrysler MODEL: Concorde 4-door sedan	CARGO: None	
263475/1/	TU	
VIN <u>& C S F U S 6 I 6</u>		
MANUFAC/BODY CODE $\frac{13}{30} \frac{29}{34}$	VEHICLE TYPE	_
- MAKE/MODEL CODE 1220	PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR	57
MODEL YEAR 1996	(20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT	
VEHICLE MASS (kg) 0 1 5 7 3	(27) COMPACT (28) INTERMEDIATE (29) FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107",	
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER	
TRAVELING SPEED (km/h) 997	(31) CHASSIS-MOUNTED CAMPER	
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE	
	(31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE	(35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI)	
(0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL	(39) TRUCK (OR SEMI) & FULL TRAILER(S) BUS (40) UNKNOWN BUS TYPE	
(5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN	(41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS)	
(8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)	
	(99) UNKNOWN	ך
	WHEELBASE (cm) (999) UNKNOWN 58 59	60

Duplicate columns 1-8 from the previous card. Module O V Format 0 2

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

Curb Weight

Rear Overhang

Average Track Width

Undeformed End Width (UEW)

Overall Length

Engine Displacement


Overall Width (OAW)

Engine: # of Cylinders

VEHICLE DAMAGE

Golf bag/clubs Cargo: 15 Kg

MEASUREMENTS IN CENTIMETERS



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

Front-End Overlap (Percent) =

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

	Vernore Decomprison	VD-1
Duplicate columns 1-8 Module V D Format 0 4 from the previous card. 9 10 11 12	VEHICLE DESCRIPTION '	VD-1
MAKE: Cheyrolet	CARGO: None	
MODEL: Silverado 1500 4x4 pick	and the second position of the second	
VIN 266 E K 1 9	Λ2 X T	29
MANUFAC/BODY CODE $ \int_{30} 13 \frac{12}{34} $	STOLEN VEHICLE	
$\frac{1}{\sqrt{3}}$	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u>
MODEL YEAR		
VEHICLE MASS (kg) Q	BODY STRUCTURE	1
ODOMETER (km) 38 3 88 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	(1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME (E.G. VW BUG)	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN) 999	(5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/h) (000) PARKED OR STOPPED	TRANSMISSION	1
(995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	64
VEHICLE TYPE	LOCATION OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE 60	61 (1) FLOOR	3
(ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH.:	(2) CONSOLE (3)_ COLUMN (7) OTHER: (9) UNKNOWN	65
(19) PASSENGER VEHICLE, TYPE UNKNOWN MULTIPURPOSE PASSENGER VEHICLE	STEERING	•
(21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	(1) POWER (2) MANUAL (9) UNKNOWN	66
TRUCK (31) PICKUP TRUCK, UNKNOWN	BRAKES	1
(32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE	(1) POWER (2) MANUAL (9) UNKNOWN	67
(99) UNKNOWN		

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	3	WHEELBASE (cm) (999) Unknown
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	2 69 8 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	3 71 8 72 73	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND <u>SHADING THE DAMAGED AREAS</u> ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
(9) UNKNOWN EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	74 	FRONT OR REAR ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card.

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

Curb Weight

Rear Overhang

Average Track Width

Undeformed End Width (UEW)

Overall Length


Engine Displacement

Overall Width (OAW)

Engine: # of Cylinders

VEHICLE DAMAGE

MEASUREMENTS IN CENTIMETERS



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Direct Damage Length (DDL) $\frac{1}{35}$ $\frac{5}{37}$ cm

Front-End Overlap (Percent) = DDI

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW) OAW

Duplicate columns 1-8 Module D from the previous card.	A Format 0 2 11 12	DAMAGE DA-1
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	13	_
IMPACT SPEED (km/h)	$\frac{9}{14}\frac{9}{15}\frac{9}{16}$	$\frac{9}{35} \frac{9}{36} \frac{9}{37}$
ESTIMATED BY	17	<u> </u> 38
CRUSH (cm)	<u>D</u> 4 8 20	$Q_{39} = 44$
CDC #1	02.FDEW.2	LYEW 4
CDC #2	98.0000.0	$\frac{9}{49} \stackrel{\cancel{8}}{\cancel{-}} \cdot \cancel{\cancel{O}} \stackrel{\cancel{O}}{\cancel{-}} \cancel{\cancel{O}} \cancel{\cancel{O}} \stackrel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel{\cancel{O}} \cancel$
from the previous card. 9 1	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	2 13	
IMPACT SPEED (km/h)	$\frac{9}{14}\frac{9}{15}\frac{9}{16}$	$\frac{9}{35} \frac{9}{35} \frac{9}{37}$
ESTIMATED BY	17	<u> </u> 38
CRUSH (cm)	$ \frac{Q}{18} \frac{2}{19} \frac{4}{20} $	$ \bigcirc \atop 39 $
CDC #1	03 RZ EW 2	<u>09.62EW.2</u>
CDC #2	$\frac{9}{28} \cdot \cancel{Q} \cdot \cancel{Q} \cdot \cancel{Q} \cdot \cancel{Q} \cdot \cancel{Q}$	$\frac{9}{49} \frac{5}{49} \cdot \cancel{Q} \cancel{Q} \cancel{Q} \cancel{Q} \cancel{Q} \cdot $
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABL (9) UNKNOWN	E (1) INVESTIGATOR (2) DRIVER (3) POLICE	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE) (999) UNKNOWN
IMPACT SPEED	(4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM	CDC
(998) NOT APPLICA (999) UNKNOWN	BLE SPECIFY:	(9800000) NOT APPLICABLE (9900000) UNKNOWN

Duplicate columns 1-8 from the previous card.

Module D A Format 0 1 12

DAMAGE

DA-2

MAXIMUM SHEET METAL CRUSH

(cm) (999) UNKNOWN

FRONT <u>0</u> 4 <u>8</u>

RIGHT SIDE Q2 4

REAR <u>Q</u> <u>Q</u> <u>Q</u>

LEFT SIDE Q

ROOF <u>Q</u> <u>1</u> <u>1</u>

OTHER

 $\underline{Q} \underline{Q} \underline{Q}$

CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE

NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER?

31

(0) NO (1) YES

EVENT NUMBER	IMPACT LOCATION (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER	IMPACT CONFIGURATION FOR CODES, SEE TABLE ON PAGE DA-3.	OBJECT/VEHICLE CONTACTED FOR CODES, SEE TABLE ON PAGE DA-4.
	(6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN		
# 1	1	13	29
#0	32	٠ ५ - ڴ	ユ ๆ
#2	37	39	
#3	37 42	<u>6</u> <u>1</u>	<u>₹</u>
#4	47	 	
#5	52		
#6	57	 	
#7	62	 	

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND <u>FRONT</u> OF CONTACTED VEHICLE (13) AND <u>SIDE</u> OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDÉSWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
 (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT

OTHER (DESCRIBE)

(99)

UNKNOWN

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

WHEELBASE

- SUB-MINI < 2286 mm (< 90°)
- 2286 2412 mm (90" 94.9")
- SUB-COMPACT 2413 - 2539 mm (95" - 99.9") 2540 - 2666 mm (100" - 104.9")
- COMPACT INTERMEDIATE 2667 - 2793 mm (105" - 109.9")
- 2794 2920 mm (110" 114.9") FULL 2921 - 3174 mm (115" - 124.9")
- LARGE LIMOUSINE > 3175 mm (> 125")

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107", E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE) (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc (52) 76 125 cc
- (53) 126 250 cc
- (54) 251 500 cc
- (55) 501 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER) (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION
- (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION (93) GUARD POST (TIMBER, METAL, CONCRETE)

- (94) CABLE, FENCE BARRIER (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

14

Duplicate columns 1-8 from the previous card. Module C R Format 0 1 1 12 CRASH RECONSTRUCTION CR-1 for ΔV					
		PRIMARY IMPACT	CASE VEHICLE SI	ECONDARY IMPACT	
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE	
EVENT NUMBER	13		2 47		
ΔV (km/h) TOTAL	<u>Q</u> 27	<u>\$\Phi_{32} 33 6_{34}\$</u>	<u>Q</u> <u>Q</u> <u>9</u> 50	Q (3 es	
LONGITUDINAL*	$\frac{-}{17} \mathcal{Q} \underbrace{1}_{20} \frac{7}{20}$	$\frac{-02}{35} = \frac{28}{38}$	+ Ø Ø Ø	$\frac{1}{69} \mathcal{O} \mathcal{O} \frac{\mathcal{O}}{72}$	
LATERAL*	<u> </u>	+023	-009	1013	
*NOTE: THESE Δ V COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76	
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>- 0 0 7</u>					
ENERGY DISSIPATED BY CRUSH (kg)		<u> </u>	<u>φο26</u>	<u>Ø</u> Ø Ø §	
RECONSTRUCTION	141290	87904			
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22		22		
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL	29 30		63 64		
(23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL		·			
NOT RECONSTRUCTED BECAUSE					
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER	,				
(05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE		· -			
(07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE					
(09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE					
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED					
MODE					
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>2</u>		<u>2</u>		
COMPUTER PROGRAM SPECIFY: WIN SM ASI-			·		

	R Format 0 2		H RECONSTRUC r EBS	TION CR-2	
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT	
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE	
EVENT NUMBER	13		2		
EBS (km/h) TOTAL	<u>Q</u> <u>2</u> <u>6</u>	$ Q_{32} \frac{3}{33} \frac{4}{34} $	$ \underbrace{\mathcal{O}}_{48} \underbrace{\frac{1}{49}}_{50} \underbrace{6}_{50} $		
LONGITUDINAL*	$\frac{-Q}{17}Q \underbrace{17}_{20}$	$\frac{-026}{35}$	$\frac{1}{51} \mathcal{Q} \mathcal{Q} \mathcal{Q}_{\frac{54}{54}}$	$\frac{1}{69} $	
LATERAL*	- 020	- Ø22	-016	+015	
*NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76	
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>-</u> <u>0</u> <u>0</u> <u>7</u>					
ENERGY DISSIPATED BY CRUSH (kj)	<u>0</u> 141	<u>Q</u> <u>Q</u> <u>8</u> <u>8</u>	<u>Ø</u> <u>Ø</u> <u>&</u> <u>6</u>	<u>Q</u> QQ8	
RECONSTRUCTION					
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22		<u>22</u>		
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64		
NOT RECONSTRUCTED BECAUSE					
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONÉ PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE	-				
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED					
MODE (1) CDC CNII Y					
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	31		2 65		
COMPUTER PROGRAM SPECIFY: WINS MASH					

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u>

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

CASE VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.


Specific Impact No.	Location of Direct Damage	Location of Field L
	Begins (Bfront bumper corner	B.C. to B.C.
2	Begins + Tem from rear axle	Begins +17cm from rear axe
		9.





- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other ___

(9) Unknown



DL <u>/50</u>

CRUSH PROFILE IN CENTIMETERS

NOTE: Each line in the table below is a separate record (card) Duplicate columns 1 - 12 for each completed line. Specific Plane **Direct Damage** Impact C_1 of Impact Length Max Field C_2 C₄ C_3 C_6 C_5 ±D Number C-Measur. (DDL) Crush Bumper 150 151 50 75 -31 ١٤ -31 -31 -18 18 Freespre 48 Ø 1 150 15 OOI 001 DQ4 031 037 ዕዛን 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 Above Sil **-** 70 18 - J 23 20 24 17 - 0 0 0 taper 0 a **(D)** 90 10

18 inner to String line set +490 cm from rear axie

Duplicate columns 1-8 from the previous card. Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u> 11 12

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

OTHER VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.


Specific Impact No.	Location of Direct Damage	Location of Field L
	Begins Ofront bumper corner	Begns + 258cm from rear axle
2	Bears Grear bumper corner	Begins + 108cm from rear axle
		9





- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other

(9) Unknown



CRUSH PROFILE IN CENTIMETERS

	NOTE: Each	line in the ta	ble below is a	separate rec				umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.		t Damage Max Crush	Field	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
	Above sill	157	C6	154	38	45	54	66	72	87	+188
	- Stringline o	d j			-23.5	-23.5	-23.5	-23.5	-23.5	-23.5	
	- taper				-20	-6	0	0	0	0	
					0	16	31	43	49	64	
1	4	157	064	154	0 00	D16	0 31	Ф43	049	064	+188
13	4	157 15 16 17	18 19 20	154 21 22 23	Ø Ø Φ 24 25 26	D 16 27 28 29	Ø31 30 31 32	D43 33 34 35	Ø 49 36 37 38	064 39 40 41	+ 188 42 43 44 45
13	14	15 16 17	18 19 20	21 22 23		27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
13	Above Sill	15 16 17	18 19 20	21 22 23	15	13	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
13	Above Sill	15 16 17	18 19 20	21 22 23	24 25 26 15 -15	27 28 29 13 -5	30 31 32 12 0	33 34 35 13	36 37 38	39 40 41	42 43 44 45
13	Above Sill -taper	15 16 17	18 19 20	21 22 23	24 25 26 15 -15	27 28 29 13 - 5	90 31 32 12 0	33 34 35 13 0 13	36 37 38 9 0	39 40 41	42 43 44 45

impact #1 String line set 118cm from ctr of vehicle
impact #2 String line set 98cm from ctr of vehicle

Duplicate columns 1-8 Module W T from the previous card.) 1 12	WHEELS AND TIRES WT-1
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RR LR LF RF RR	0 = 0 0 5 T J J J	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF P 2 4 5 7 5 R 1 6 RF P 2 4 5 7 5 R 1 6 RR P 2 4 5 7 5 R 1 6 LR P 3 4 5 7 5 R 1 6 LR P 3 4 5 7 5 R 1 6
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 21 3 24	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:			

Duplicate columns 1-8 Module F T Format 0 from the previous card. 9 10 11		FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>8</u> 21
MAIN TANK LOCATION MAIN FILLER CAP LOCATION	3 13 14 16 1 13 17 19	AUXILIARY TANK LOCATION AUXILIARY FILLER CAP LOCATION	\(\frac{\mathbb{g}}{22} \frac{\mathbb{g}}{24}\) \(\frac{\mathbb{g}}{25} \frac{\mathbb{g}}{27}\) \(\frac{\mathbb{g}}{25} \frac{\mathbb{g}}{27}\)
MAIN TANK MATERIAL	3 20	AUXILIARY TANK MATERIAL	28

TANK AND FILLER CAP LOCATION CODES

FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

Duplicate columns 1-8	
from the previous card.	

Module	F		Format 0	_1_
	9	10	11	12

FUEL LEAKAGE FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.



	l	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15			. 		21
#2	22 23					29
#3	30 31					37
#4	38 39					45
#5	46 47	—				53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP) (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP) (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT. COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

I COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED
- (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format C from the previous card.		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP PAC</u> (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES	17

PROVIDE NOTES IF FIRE OCCURRED.

(0) NO (1) YES (9) UNKNOWN

Duplicate columns 1-8 Module E D Format (from the previous card. 9 10 11	© 1 EXTERIOR DAMAGE	ED-1
HOOD PERFORMANCE FOR THE FOLLOWING, USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE (0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OTHER:	<u>9</u> 26
HOOD LATCH(ES)RELEASED -DAMAGED -JAMMED	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED 14 COUPLINGDAMAGED (USE CODES	<u>9</u> 27
HOOD HINGESLEFT, DAMAGED	15 FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	<u>9</u> 28
-LEFT, SEPARATED (COMPLETE) -RIGHT, DAMAGED -RIGHT, SEPARATED (COMPLETE) HOOD REMAINED ON VEHICLE	ENG COMPART TELESCOPING UNIT TYPE OF UNIT (00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED (97) OTHER: (98) EQUIPPED, TYPE UNKNOWN (99) UNKNOWN IF EQUIPPED	8 8 29 30
REAR EDGE OF HOODELEVATED -CONTACTED WINDSHIELD -PENETRATED WINDSHIELD	ORIGINAL LENGTH (mm) F (OR H): TELESCOPED LENGTH (mm) G:	
HOOD LATCH LOCATION (1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN	DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.) (888) NOT COLLECTED	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	(991) NOT MEASURED/NO	8 8 8 33


		Exterior Damage	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	₫	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	4	USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR)	
-A-PILLAR, UPPER LOWER		(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	Ø 43 8 44
-B-PILLAR, UPPER LOWER -C-PILLAR, UPPER	37 38 <u>0</u>	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
LOWER	39 <u>40</u>	-FRONT	45 <u>45</u> <u>8</u> 46
-D-PILLAR, UPPER	8 41 8 42		

		EXTERIOR DAMAGE	ED-3
REAR DOOR REAR DOOR TYPE (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN	<u>Q</u>	OTHER REAR DAMAGE WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN SPARE TIRE (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION	<u>8</u> 51
One-way Two-way Clamshell Single door Double door		(3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED (9) UNKNOWN TRAILER HITCH TYPE (0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES	7 52
HOW DID DOOR OPEN DURING COLLISION? (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN DOOR JAMMED CLOSED (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	<u>8</u> 48	(5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. PJU) (7) OTHER (E.G. CLEVIS-AND-PIN) Reesc (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	Φ

-		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u> 54	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	4 55	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN	
LOWER	4	-FRONT -REAR	
-B-PILLAR, UPPER	4 57	DOORS JAMMED CLOSED-	65 66
LOWER	7 58	USE CODES: (0) NO (1) YES	
-C-PILLAR, UPPER	<u><u> </u></u>	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	1
LOWER	• O _ • •	-FRONT	67
-D-PILLAR, UPPER	$\frac{9}{61}$		68
LOWER	8/2	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	<u>8</u>

		EXTERIOR DAMAGE	ED-5
- WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICLE	:
WINDSHIELD CRACKED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70	SHADED SOLAR - SAFTY LO FLO-LITE	
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u>	ASI F LAMINATED	
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	Q	WINDSHIELD CODE	a7
EXTENT OF BOND SEPARATION		(97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN	74 75
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN	73	DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	\$ 76

LOCATE AREA OF WINDSHIELD INTEREST OR DAMAGE WITH DIMENSIONS (VERTICAL & HORIZONTAL) ON THIS DIAGRAM OF THE WINDSHIELD AS VIEWED FROM <u>INSIDE</u>.



L


င

R

Duplicate columns 1-8 Module S C Format 0 from the previous card. 9 10 11	1 12	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	13	STEERING WHEEL POSITION AT TIME OF COLLISION IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 9 2	i ewed
- NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AHEAD) O'CLOCK = 99 UNKNOWN	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70-74 CHALLENGER, 70-74 CAPRI, 71-77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	<u>3</u>	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u></u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u></u>	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 22

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE TYPE OF DEVICE * (IF 27 OR 28) (00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN ORIGINAL LENGTH (mm) C:	8 8 24	STEERING WHEEL (CONTINUED) STEERING WHEEL HUB DAMAGE (0) NONE (1) OCCUPANT CONTACT (2) AIRBAG (3) OTHER (9) UNKNOWN	<u>Q</u>
COMPRESSED LENGTH (mm) D: BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR COMPRESSION (OR EXTRUSION) (mm) C - D (OR E) (TOLERANCE: ±10) (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN * (ADD A & B FOR TOTAL COMPRESSION) SHEAR CAPSULE SEPARATION (mm) S (USE AVG. OF LEFT & RIGHT CAPSULES.) LT:	8 8 8 25 Z7		
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u> </u>		
COLUMN LATERAL ROTATION (0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	$\frac{\mathbf{x}}{\mathbf{Q}}$		

				Inti	RUSION IT-1
Location Intrusio	of i Intrude	ed Component	Compai Valu	(All Measurements Are in Centimeters) rison Intruded le - Value = Intrusion	Dominant Crush . Direction
11	W/S h	eader	113	-107 = 6	vertical
11	A- P		113	- 97 = 17	1,
11	Side		114	- 102 = 12	٠,
11	Roof		118	- 108 = 10	5
-13	Toepo		63	- 45 = 18	longitudinal
				- =	, so si con i con
				- =	
				=	
				- =	
				= =	
				=	
				=	/
genta jegov erekul. 1909 gjele					
	T		OCCUPANT (CONTACT WORKSHEET	
Contact	Interior Component Contacted	Occupant No. if Known	Body Region if Known	Supporting Physical Evidence	Confidence Level of Contact Point
Α	Interer dwor	-	hip	large scuff-mark	1
В	underside of Column		Knee	souff-mark	1
С	Ctr. Console	1	hip	Small scuff-mark	2
D	Ruof	1	head	blood (rust?) Smear	3
E					
F					
G					
Н					
ı					
J					



CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1) LEFT	(3) RIGHT		INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
(0) LEFT SPAC	& (2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4) ENTIF	E VEHICLE WIDTH		CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY



CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	•
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR .
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE (46) OTHER (E.G. SPARE TIRE,
- JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF <u>ALL</u> THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

- (50)WINDSHIELD HEADER A-PILLAR ROOF SIDE RAIL
- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR WINDSHIELD HEADER
- (53)DOOR PANEL B-PILLAR ROOF RAIL
- (54)DOOR PANEL A-PILLAR ROOF RAIL
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- (56)ROOF RAIL
 A-PILLAR
 B-PILLAR
 WINDOW FRAME
- (57)ROOF RAIL A-PILLAR B-PILLAR C-PILLAR DOOR PANEL
- (58)ROOF ROOF RAIL WINDOW FRAME DOOR PANEL
- (59)BACKLIGHT HEADER ROOF C-PILLAR THIRD SEAT-BACK

- (60)ROOF
 ROOF RAIL
 A-PILLAR
 B-PILLAR
 C-PILLAR
 WINDOW FRAME
 DOOR PANEL
 FLOOR PAN
- (61)INSTRUMENT PANEL TOE PAN WINDSHIELD HEADER A-PILLAR ROOF RAIL WINDOW FRAME DOOR PANEL ROOF
- (62)ROOF
 ROOF RAIL
 C-PILLAR
 WINDOW FRAME
 FLOOR PAN
 SECOND SEAT
 DOOR PANEL
- (63)ROOF RAIL
 ROOF
 B-PILLAR
 WINDOW FRAME
 FLOOR PAN
 DOOR PANEL
 SECOND SEAT
 FRONT SEAT
- (64)ROOF RAIL
 ROOF OR CONVERTIBLE TOP
 A-PILLAR
 B-PILLAR
 WINDOW FRAME
 WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER ROOF SIDE RAIL
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	e <u>I</u> <u>T</u> Format <u>0</u>	1 12			Inte	RUSION	IT-5
(0) NO <u>DO NOT</u> ANSWER NE	XT QUESTION. <u>SKIP PA</u>			(0) NO	COMPLETE PA		14
from the previous card.	9 10 11	12	olicate column	s 1 - 12 for eac	h completed li	ne.	
CODES	<i>FOR</i> B, F, G, H, I, .	J ON PAGE	T TO RIGHT IT-3				·S.
A B C INTRUDING INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT			G MAXIMUM INTRUSION Z AXIS (cm)	H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21	22-23	24-25	26-27	28-29	30-31	32-33
<u>0 1 1 08</u>	3 00	D D	17	QQ	00	$\Phi\Phi$	00
02 11 14	3 00	$\overline{0}$	12	$\Phi \Phi$	$\underline{\mathscr{O}}\underline{\mathfrak{O}}$	00	00
03 11 15	<u>3</u> <u>Q</u> <u>Q</u>	$\overline{0}$	10	$\overline{\Phi}$ $\overline{\Phi}$	$\Phi \Phi$	00	00
04 11 07	3 00	<u>O</u> <u>O</u>	06	$\Phi \Phi$	$\Phi \Phi$	00	00
<u>0 5 1 3 03</u>	1 18	$\Phi \Phi$	ΦΦ	$\overline{\Phi}$	$\overline{\Phi}$	<u> </u>	00
06	VAS THERE OCCUPANT COMPARTMENT INTRUSION? 1 12 12 13 12 13 14 15 16 17-18 19 20-21 22-23 24-25 26-27 28-29 30-31 32-33 1 1 15 3 20 0 0 0 0 0 0 0 0						
0 7 NOTE: USE ADDITIONAL PAGE IF MORE TH	HAN 7 INTRUSIONS.			——			
Duplicate columns 1-8 Module from the previous card.							
SIDE DOOR INTRUSION	DOO	R INTRUS SION	ION, CODE DAMAGED	COMPONE DAMA	ENT AGED NENT 2	CODES	
CODES FOR CAUSE: 13 15 (1) DIRECT IMPACT 16 18 (2) INDUCED DAMAGE	B	_	_ _ _	29	5 (- (- (- (1) A-PILLAR 2) B-PILLAR 3) C-PILLAR 4) LATCH/STRI 5) HINGES 7) OTHER:	_
	D			37	_ (•	

Duplicate columns 1-8 from the previous card. INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY

A	B OCC.	C INTRUDING COMPONENT	EVENT		F MAXIMUM INTRUSION		H	INJURY	J	K
NUMBER	SPACE NO.	OR OBJECT	NO.	X AXIS (cm)	Y AXIS (cm)	Z AXIS (cm)	NUMBER	NUMBER	NUMBER	NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
0 9										
1 0										
11			_					· .		
1 2										
1 3										
1 4										
<u>1</u> <u>5</u>										
1 6										
1 7										
1 8										
1 9			_		·					
20										
2 1			_							
22			_							
2 3										
2 4										
2 5										
										-

Duplicate columns 1-8 from the previous card.	Modu	le <u>l</u> <u>D</u> 9 10	Format <u>0</u> <u>1</u>	ln	TERIOR DAMAGE	ID-1
co	(1) NO) YES) NO, and	d OCCUPANT CONTACT	(4) YES, and C (8) NOT APPL (9) UNKNOWN		
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF			FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE		INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLET HEATER OR A/C DUCTS RADIO OTHER: *	
OTHER: *	43	40 42 44			REAR WINDOW WINDOW HEADER CONSOLES VERTICAL ROOF	

^{*} MORE THAN ONE ITEM MAY BE NOTED.


Duplicate columns 1-8 Module S T from the previous card.		2 12	SEATS	(ST-1
FRONT SEAT	DRIVER	PASSEN'R	FRONT SEAT-BACK	Driver	PASSEN'R
TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE	<u>Ø</u> 5	<u>Ø \$</u>	SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	30	31
(97) OTHER: (99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	19		LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	34	J
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	21	22	RECLINER MECHANISM HELD (0) NO (1) YES	36	<u></u>
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	<u>So</u> 2₄	(8) NOT APPLICABLE (9) UNKNOWN	30	3,
FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	<u>P</u>	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	38	39
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	27	7	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN ADJUSTMENT AT CRASH		
FRONT SEAT ROTATION (0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	Q 28	29	(1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	42	43


			Se	EATS S	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE (0) NONE (RIGID)	DRIVER	Passen'r	SECOND SEAT (CONT.) CENTER ARMREST DAMAGED		
(1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN ADJUSTMENT PROVIDED (1) 2-WAY (2) 4-WAY	3	47 3	(0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	2	<u>s</u>
(3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN			SECOND SEAT-BACK LOCKS	LEFT	Rіснт
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	50	51	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	1	a
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	8 52	8 53	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	61 1 63	8
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	3 54	3 55	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	67 67	66 <u>68</u>
SECOND SEAT TYPE OF SECOND SEAT (0) NONE	LEFT	Rіgнт	EQUIPPED BACKREST DAMAGED	0 69 6 71 36	72 8
(1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT	2/56	$\frac{2}{57}$	CUSHION DAMAGED	73	8 74
(6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u> 58	<u>Ф</u>	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	1 7	5

Duplicate columns 1-8 from the previous card. Module A B Format 0	1 12	AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	16 O 17
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDNOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	15	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN IF EQUIPPED OR CONDITION	8/18
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	8 21
MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	$\frac{\mathcal{O}}{\overline{20}}$	MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	8/22


AIRBAG AB-2

AIRBAG NUMBER ON DRIVER SIDE:





AIRBAG NUMBER ON PASSENGER SIDE:



NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 Module O C Format 0 from the previous card.	1 2	OCCUPANT INFORMATION (OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	$\frac{65}{\frac{20}{20}}$ $\frac{25}{22}$
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN HEIGHT (cm) (999) UNKNOWN SEX (1) MALE (2) FEMALE (9) UNKNOWN	$ \frac{114}{24} = \frac{1}{25} = \frac{1}{28} $ $ \frac{193}{27} = \frac{1}{30} $
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>Ø</u> 4/31 22
POSTURE (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT	18 19	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN	10
(50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN		NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	35


		OCCUPANT INFORMATION	OC-
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	2 36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	3
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG NOT DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE LAP & UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	3 37 38 1 39	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED IF OCCUPANT WAS EJECTED, DESCRIBE IN DETAIL BELOW: HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED	98

OCCUPANT EYEWEAR OCCUPANT EYEWEAR OCCUPANT EYEWEAR ON NONE ON NONE ON NONE ON NONE ON NOT APPLICABLE OCCUPANT INFORMATION ON INTERVIEW OCCUPANT INFORMATION OCCUPANT

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.





INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

OCCUPANT INJURY CLASSIFICATION


Duplicate columns 1-8 from the previous card.

						PRIM	ARY (OIC		A	ssoc	IATE	OIC		СОММЕ	NTS
OCCUPANT NUMBER	INJURY NUMBER	PROBAL START V IN 1ST C	BILITY (HOR WITH MOST CONTACT AI	IN ORDER OF IZONTALLY) . PROBABLE REA COLUMN. BLE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 10	BODY REGION 1	ASPECT O	LESION 3	SYSTEM/ORGAN 4	SEVERITY 10		
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30		
\mathcal{O}	ΦI	99			R	L	L	I	1			_				
↑	Q Z	99			R	L	L	I	1							
	03	34			C	<u>L</u>	<u>C</u>	I	1							
	Ø4	34			5	L	(I	1							
	05	48			L	L				_						
											_		_			
						_										
		— —			-	_	_	_	_			_		-		
نع					-		_				_	_	_	-		
or each i					-				_	_		_	_	-		
umber" f						_	_	_			_	_	_	-		
upant N					-	_	_					_		-		
Duplicate "Occupant Number" for each line.					_	_		_		_		_		_		
- Duplic					_	_		_		_	_	_		_		
					_				_		_			_		
					-				_	_		_				
					_	_	_	_	_			_				
					_	_	_		_	_	_			_		
						_		-		_			_			
1			GES IF NEC										·			

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	HARDWARE ON SIDE OR DOOR
· · -/		(13)	ARMREST ON SIDE OR DOOR
(05)	INCTOLINENT DANEL (COCCIEIC ADEA LINICAIONAI)		
(05)		(24)	COAT HOOK
(54)	UPPER INSTRUMENT PANEL (X)		
(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)	(21)	· · ·
	ASH TRAY (INSTRUMENT PANEL)	(,	······································
(81)	· · · · · · · · · · · · · · · · · · ·	(==)	
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	- (14)	A-PILLAR
		(15)	B-PILLAR
(57)	BENEATH INSTRUMENT PANEL		C-PILLAR
(53)	PARCEL TRAY	(17)	D-PILLAR
(48)	KNEE RESTRAINT	_	
(86)	VERTICAL CONSOLE	FLOOR	
		(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
(20)	POOT CONTROLS (MOL. I ANNING BRAKE I EDAL)	· · ·	
		(44)	
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE
(65)	STEERING WHEEL	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)	STEERING WHEEL COLUMN	(91)	· · · · · · · · · · · · · · · · · · ·
		(31)	MON AREE
(59)	TRANSMISSION LEVER ON COLUMN		
		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	
		` '	the state of the s
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	COAT HOOK
(67)	IGNITION KEY	(18)	DOME LIGHT
(06)	MIRROR	(39)	BACKLIGHT HEADER
	HEATER OR AIR CONDITIONING DUCTS	• •	
(04)		(68)	
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	ROLL BAR
(08)	RADIO (BUILT IN)		
(58)	ADD-ON TAPE DECK, RADIO, A/C	EXTERIO	OR SURFACE OF CASE VEHICLE
	ROOF MOUNTED CONTROLS/CONSOLES		OUTSIDE SURFACE OF CASE VEHICLE
(68)	HOUP MOUNTED CONTROLS/CONSOLES	(37)	
_			(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
		(/	OUTSIDE MIRRORS, ANTENNA, TRIM)
(23)			· · · · · · · · · · · · · · · · · · ·
(39)		(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
INTERIO	R-GENERAL	• •	
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)	REVOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN		AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(07)	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT	٧/	OUTSIDE MIRRORS, ANTENNA, TRIM)
		(70)	· · · · · · · · · · · · · · · · · · ·
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
		(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)		
		(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)		(76)	OUTSIDE SURFACE OF OTHER VEHICLE
	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	FRONT SEAT CUSHION		
1 7	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK	(77) (78)	TIRES OF OTHER VEHICLE
(49)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT	(77) (78) (79)	TIRES OF OTHER VEHICLE GROUND WATER
1 7	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT	(77) (78)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(49) (89)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM	(77) (78) (79)	TIRES OF OTHER VEHICLE GROUND WATER
(49)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE	(77) (78) (79) (80)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.)
(49) (89)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE	(77) (78) (79) (80)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(49) (89) (33) (34)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING	(77) (78) (79) (80) PENETR	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS
(49) (89) (33) (34) (87)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG)	(77) (78) (79) (80) PENETR (61)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE
(49) (89) (33) (34) (87) (47)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(77) (78) (79) (80) PENETR (61)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS
(49) (89) (33) (34) (87) (47) (46)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS	(77) (78) (79) (80) PENETR (61) (72)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE)
(49) (89) (33) (34) (87) (47)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS	(77) (78) (79) (80) PENETR (61) (72)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE
(49) (89) (33) (34) (87) (47) (46)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT	(77) (78) (79) (80) PENETR (61) (72) MISCELL	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE)
(49) (89) (33) (34) (87) (47) (46) (48) (30)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE)
(49) (89) (33) (34) (87) (47) (46) (48) (30) (42)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE)
(49) (89) (33) (34) (87) (47) (46) (46) (48) (30) (42) (43)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38) (90)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE
(49) (89) (33) (34) (87) (47) (46) (48) (30) (42)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED
(49) (89) (33) (34) (87) (47) (46) (46) (48) (30) (42) (43)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38) (90)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED
(49) (89) (33) (34) (87) (47) (46) (48) (30) (42) (43) (31) (32)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S)	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38) (96) (96)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTED, UNKNOWN CONTACT
(49) (89) (33) (34) (87) (47) (46) (48) (30) (42) (43) (31) (32) (52)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S) INTERNAL FLYING GLASS (FROM ANY SOURCE)	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38) (90) (96)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTED, UNKNOWN CONTACT IMPACT FORCE, "WHIPLASH",
(49) (89) (33) (34) (87) (47) (46) (48) (30) (42) (43) (31) (32) (52)	FRONT SEAT CUSHION REAR SEAT CUSHION & BACK ARMREST ON SEAT UNDER SEAT BOTTOM RESTRAINT SYSTEM HARDWARE RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S)	(77) (78) (79) (80) PENETR (61) (72) MISCELL (00) (38) (90) (96) (97) (98)	TIRES OF OTHER VEHICLE GROUND WATER EXTERIOR OBJECT (NOT VEHICLE, GROUND, OR WATER. PLEASE DESCRIBE.) ATING OBJECTS OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTED, UNKNOWN CONTACT

Injury Classification IC-3



CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY 5 SYSTEM/ORGAN 4 LESION 3 ASPECT 2 BODY REGION 1

5 SEVERITY (OR *AIS*, ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN















N 18800













d Available



PN 18800#14





est Availab



et Availah











118800#22































18800#3





























PN 18800#51